

| | |
|----------------------|--|
| Skin contact: | Wash with soap and water. If symptoms develop and persist, get medical attention. |
| Eye contact: | Get medical attention. Immediately flush eyes with plenty of water for at least 15 minutes. |
| Ingestion: | Aspiration may cause pulmonary edema and pneumonia. Do not induce vomiting. Get medical attention. |

5. FIRE FIGHTING MEASURES

| | |
|--|--|
| Flash point: | > 93 °C (> 199.4 °F) |
| Autoignition temperature: | Not determined |
| Flammable/Explosive limits - lower: | Not determined |
| Flammable/Explosive limits - upper: | Not determined |
| Extinguishing media: | Carbon dioxide, Dry chemical, Foam, Water spray or fog |
| Special firefighting procedures: | None |
| Unusual fire or explosion hazards: | None |
| Hazardous combustion products: | Oxides of carbon |

6. ACCIDENTAL RELEASE MEASURES

Use personal protection recommended in Section 8, isolate the hazard area and deny entry to unnecessary and unprotected personnel.

| | |
|-----------------------------------|--|
| Environmental precautions: | Do not allow material to contaminate ground water system |
| Clean-up methods: | Follow all local, state, federal and provincial regulations for disposal. Scrape up as much material as possible. Clean residue with soap and water. |

7. HANDLING AND STORAGE

| | |
|------------------|--|
| Handling: | Wash thoroughly after handling. Keep container closed. Avoid contact with eyes, skin and clothing. |
| Storage: | Keep in a cool, well ventilated area. |

For information on product shelf life contact Henkel Customer Service at (800) 243-4874.

8. EXPOSURE CONTROLS / PERSONAL PROTECTION

Employers should complete an assessment of all workplaces to determine the need for, and selection of, proper exposure controls and protective equipment for each task performed.