


MOLLE Clip

Installation Instructions:

STAR-PAN VI

808-250

TS8-429



Remove and replace the two topmost screws, and the two screws second from the bottom using the following:

Torque Value - 64 ± 8 IN-OZ

Driver Size - NO.1 PHILLIPS

Do not remove the remaining four screws in the middle portion of the hub, or the two bottommost screws.