



SERIES 927-072  
**ITS-Ex Hazardous Zone Connectors**  
 Polarization



**INSERT ROTATION ALTERNATE POSITIONS**

Arrangement	$\alpha \pm 2^\circ$			
	W	X	Y	Z
10SL-3				
10SL-4				
18-1	70	145	215	290
18-3	35	110	250	325
18-4	35	110	250	325
18-5	80	110	250	280
18-6				
18-06	180			
18-7				
18-8	70			290
18-9	80	110	250	280
18-10		120	240	
18-11		170	265	
18-12	80			280
18-13	80	110	250	280
18-19		120	240	
18-20	90	180	270	
18-22	70	145	215	290
18-30				

Arrangement	$\alpha \pm 2^\circ$			
	W	X	Y	Z
36-3	70	145	215	290
36-4	70	145	215	290
36-5		120	240	
36-6	35	110	250	325
36-7	80	110	250	280
36-8	80	110	250	280
36-9	80	125	235	280
36-10	80	125	235	280
36-14	90	180	270	
36-15	60	125	245	305
36-18				
36-22	80	110	250	280
36-35				
36-54 = 36-B39	67			
36-66	110	250	260	280
36-74				
36-77	45	90		
36-A7				
36-A35				
36-A51	45	135	225	315
36B-78	35	106	254	325
36D-78	35	106	254	325

**Insert Rotation (front view)**

