



MOLLE Clip

Installation Instructions:

STAR-PAN II Connectorized

808-194-1



Remove and replace all six screws on the hub using the following:

Torque Value - 32 ± 8 IN-OZ

Driver Size - .050" HEX